Polycom

Polycom is pleased to provide these supplemental release notes to the Polycom HDX Systems software version 3.1.11_03

These release notes provide notice of the items included in the hot fix provided to you by the Polycom Global Services (PGS) organization. It is intended for you as a fix to your specific issue and should not be provided to other groups without the consent of PGS. This assures the integrity of all systems using this Hot Fix is retained.

This Hot Fix contains these items:

Hotfix number	Jira record Videsc-ID	Siebel record ID	Summary
	VIDESC-16740	1-4868043571	HDXv3.1.11_HF1 - During MP conference with HDXA--HDXB(MCU)--SX20 and PVEC is enabled, people video is corrupted on HDXA monitor when SX20 is active speaker
	VIDESC-17012/15913	1-5545761608	HDX reboots 20 seconds after receiving content from a Lifesize ICON 600 codec through a Lifesize Media Server
	VIDESC-17094	1-5502691551	A Qualys security test ran on HDX 3.1.11 returns many threats despite installing 3.1.11_2 and disabling TLSv1 over telnet
	VIDESC-16853	1-5158754281	Network Vulnerability Scans are showing SSL Cipher Vulnerabilities

Supplemental Release Notes
Polycom ® HDX Systems, Version 3.1.11_03 Hotfix

Copyright Information

Disclaimer

Trademark Information