
Advisory: HP Z420/Z620/Z820 Workstation - May Not Be Able To Update System BIOS



Version: 1

Advisory: HP Z420/Z620/Z820 Workstation - May Not Be Able To Update System BIOS

NOTICE: The information in this document, including products and software versions, is current as of the Release Date. This document is subject to change without notice.

Release Date: 2013-10-31 Last Updated: 2014-01-30

DESCRIPTION

A user is not able to update a System BIOS to new version 02.XX or 03.XX when an HP Z420, Z620, or Z820 workstation has the System BIOS version older than 1.07.

SCOPE

Information in this document applies to the following:

Systems:

- HP Z420 Workstation
- HP Z620 Workstation
- HP Z820 Workstation

Operating Systems:

• Non-OS Specific

System BIOS: older than version 1.07

RESOLUTION

To resolve this issue, install a System BIOS version 01.23 (or 01.20 for Z820) and then the new version	
02.XX or 03.XX. NOTE	To determine the BIOS family and BIOS date, press F10 on the target workstation during Power On to run the Computer Setup Utility,
	and then select File/"System Information". This information can be saved into a text
	file on a USB flash media device by selecting File/"Save to Removable Storage

Device".

NOTE You can download HP Z420/Z620 Workstations System BIOS VERSION: 01.23 Rev. A at:

Advisory: HP Z420/Z620/Z820 Workstation - May Not Be Able To Update System BIOS

ftp://ftp.hp.com/pub/softpaq/sp64501-65000/sp64701.exe ftp://ftp.hp.com/pub/softpaq/sp64501-65000/sp64701.html ftp://ftp.hp.com/pub/softpaq/sp64501-65000/sp64701.cva

HP Z820 Workstations System BIOS VERSION: 01.20 Rev. A at: ftp://ftp.hp.com/pub/softpaq/sp61001-61500/sp61312.html ftp://ftp.hp.com/pub/softpaq/sp61001-61500/sp61312.exe ftp://ftp.hp.com/pub/softpaq/sp61001-61500/sp61312.cva

WARNING : After installing a 2.xx or 3.xx BIOS onto the system, the system will not be able to flash back to a 1.xx BIOS.

Hardware Platforms Affected: HP Z420 Workstation, HP Z620 Workstation, HP Z820 Workstation Operating Systems Affected: Not Applicable Software Affected: Not Applicable Support Communication Cross Reference ID: IA03993436

©Copyright 2014 Hewlett-Packard Development Company, L.P.

Hewlett-Packard Company shall not be liable for technical or editorial errors or omissions contained herein. The information provided is provided "as is" without warranty of any kind. To the extent permitted by law, neither HP or its affiliates, subcontractors or suppliers will be liable for incidental, special or consequential damages including downtime cost; lost profits; damages relating to the procurement of substitute products or services; or damages for loss of data, or software restoration. The information in this document is subject to change without notice. Hewlett-Packard Company and the names of Hewlett-Packard products referenced herein are trademarks of Hewlett-Packard Company in the United States and other countries. Other product and company names mentioned herein may be trademarks of their respective owners.

Provide feedback

Please rate the information on this page to help us improve our content. Thank you!

Was the information on this page helpful?

Very helpful Somewhat helpful Not helpful

United States

About HP

Contact us Newsroom Investor relations Living Progress Accessibility Events HP Labs Jobs Social Media

Consumer support forum Enterprise business community Developer community Corporate blogs

🗗 in 💟

HP Partners Become a partner Find a reseller PartnerOne

Customer Support

Power cord replacement Download drivers Register your product Authorized service providers Training & certification Product recycling

Home | Email sign-up | Site map | Privacy | Cookies & ad choices | Terms of use | Recalls © 2014 Hewlett-Packard Development Company, L.P.

View mobile site