

System board (motherboard) printed circuit assembly, 2S/DDR3 1333 MHz memory (Patsberg)	SP P/N	619562-001 v1
<p>(HP errors below... both motherboards can run proper DDR3 <u>1866 MHz</u> memory)</p> System board (motherboard) assembly - Supports 2S/DDR3 1333 MHz memory (Patsberg)	SP P/N	708610-001 v2
<p>(No OS ID encoded in this MB's firmware)</p>		"No DPK"
System board (motherboard) assembly - Supports 2S/DDR3 1333 MHz memory (Patsberg) - For Windows 8 Professional		708610-601 v2
<p>(This MB's OS ID encoded in its FW allows load of HP OEM W7 Pro64 & W8.x Pro64)</p>	SP P/N	"W8 Pro"