

[Enable/Disable Sleep Mode on page 179](#)

[Disk Wipe DoD 5220.220M on page 180](#)

Sanity level

Insecure mode

1-pass mode

5-pass mode

Disk Wipe (DOD 5220.220M)

[Hard Disk Recovery Utility on page 182](#)

[Show/Hide Touch Control Panel Information on page 183](#)

[Enable/Disable Port 280 on page 184](#)

[File System Check on page 185](#)

[I/O Tests on page 186](#)

[Rewinder Adjust on page 188](#)

Adjust Rewinder 1

Adjust Rewinder 2

[Disable Upper Roll Cover on page 189](#)

[Enable Upper Roll Cover on page 190](#)

[Special Cutter Mode on page 191](#)

[Scanner Validation on page 191](#)

[Adjustment scanner Y-Axis scale on page 199](#)


[Reset Access Control on page 203](#)

[Uninstall Applications on page 203](#)


[Accounting Mode on page 203](#)

## Entering the Service Utilities Menu

1. From the Home Screen press the Information icon on the top left corner of the screen. For information regarding the Touch Control Panel keys, see [Using the Touch Control Panel \(MFP only\) on page 2](#) or .
2. From the product Information Area, press the Main Menu / tool icon on the bottom right corner of the screen.




3. Scroll down to the lowest menu option and press on the **Service menu** option.



4. Enter the 4-digit 1st level access code "3174" and press **OK**.



5. Press on the **Service utilities** menu option.



6. From the **Service utilities** menu you can scroll up and down the available utilities. Press on the selected menu option.

